



# APPLICATION GUIDE

## General Notes

- Ensure to read the TECHNICAL DATA SHEET, the PREPARATION GUIDE and the APPLICATION INSTRUCTIONS thoroughly first.
- Always wear the appropriate personal protection equipment.
- It is recommended to do a test patch first to determine the suitability of the product.
- Do not apply when the ambient temperature is below 15c or above 28c.
- It is always advisable to apply sealers in the afternoon and in the shade.
- Do not apply in direct sunlight when the temperatures exceed 28c.
- The substrate must be cool to touch before applying any sealer or coating.
- Do not apply if rain is imminent in the following 24 hours of application.

## Application

- Always follow the manufacturer's guidelines for coverage.
- H2O Penetrating Sealer should be applied using a 10mm nap roller, applicator or back pack sprayer.
- Apply a saturation coat and allow to soak. If the product soaks in before 10 mins, apply a second application while still wet. Once dried it will not accept another coat. It is ideal to see the surface wet with product for approx 10 mins.
- After 10 mins, remove any excess sealer and move to the next area. Repeat the process.
- DO NOT ALLOW EXCESS PRODUCT TO DRY ON THE SURFACE AS IT WILL GO WHITE.
- Keep dry for a minimum of 12 hours.
- Do not walk on for a minimum of 6 hours.